

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Fig.1




Fig. 2




Fig. 1 is a cross-sectional view of a mechanical assembly. The assembly includes a top plate 12 with a flange 12e. Below the plate is a component 15 with a vertical section 15b and a horizontal section 15c. A central vertical shaft 51 is shown, with a section 51d. The shaft is surrounded by a housing 25, which has a section 41. The housing is secured by a bolt 31 and a nut 32. A spring 33 is located between the housing and a base 54. The base 54 has a section 51b. The assembly is mounted on a base 24, which has sections 24f, 24g, 24i, and 24j. The base 24 is surrounded by a housing 28, which has sections 28a, 28c, 28d, 28e, and 28f. A section 15f is also shown.

Fig.4




Fig.5




Fig.6




Fig.7




Fig.8

